

INDUSTRIAL MANUFACTURER – AUTOMOTIVE



TRELLEBORG VIBRACOUSTIC

- Markets: Industry & Manufacturing
- Country: Germany
- Courtesy of: Superior Products Germany

PROJECT DESCRIPTION

The inside temperature during vulcanization in this mold is 175°C.
Problem is that the outside temperature is +/- 165°C, creating a high safety risk and energy losses by radiation.

COATING SOLUTION

7mm Hot Surface Coating was applied with a spray gun on the outside.

RESULT

Outside temperature dropped to 63°C.

PRODUCTS WE USED

Hot Surface Coating™