

## **RIVER BARGE - PRIVATE OWNER**



### **PRIVATE OWNER**

- Markets: Shipping & Transport
- Country: Belgium
- Courtesy of: Superior Products Belgium

### **PROJECT DESCRIPTION**

Inland barge suffering from a rust problem due to general wear and tear.

### **COATING SOLUTION**

First RUST GRIP was applied in two coats, followed by SUPER THERM. Only preparation was removing of scale rust and loose paint by hand tools.

### **PRODUCTS WE USED**

**Super Therm®**  
**Rust Grip®**